

PHOTOGRAPH LOG

Project Name:Gold King Blowout

Site Location: Silverton, CO

Project No.

0267

Photo No.

Date: 08/30/2015

Direction Photo Taken:

NW

Description:

Upper Gladstone work area from southwest end. Note location of buildings and old lime silo. Haul truck is beside temporary sludge repository, and the road on the right will be for temporary waste rock storage.



Photo No. 2

Date: 08/30/2015

Direction Photo Taken:

W

Description:

Facing south from wood building along rerouted access road.



Page 1 of 3



PHOTOGRAPH LOG

Project Name:

Gold King Blowout

Site Location: Silverton, CO

Project No. 0267

Photo No.

Date: 08/30/2015

Direction Photo Taken:

Ν

Description:

Two site buildings, personnel dry room in wood building, lime silo and treatment building in background.



Photo No.

Date: 08/30/2015

Direction Photo Taken:

Ν

Description:

Potential location for ponds 1 and 2 left of the lime silo and treatment building. The edge on the left is a steep slope into Cement Creek.





PHOTOGRAPH LOG

Project Name:

Gold King Blowout

Site Location: Silverton, CO

Project No. 0267

Photo No. **5**

Date: 08/30/2015

Direction Photo Taken:

Ν

Description:

Facing north from near lime silo, road would be removed if ponds are installed in upper Gladstone.



Photo No.

Date: 08/30/2015

Direction Photo Taken:

S

Description:

Facing south from near lime silo. Overall view of area with the dry room building visible on the left, this is the potential area for water treatment and/or ponds.





N N

200 ft

Google earth

© 2015 Google